



Photo 1 – View of airplane resting in EMAS system. (Courtesy of AIG)



Photo 2 – Right profile view of airplane resting in EMAS system. (Courtesy of AIG)



Photo 3 – Left quarter view of airplane resting in EMAS system. (Courtesy of AIG)



Photo 4 – View of nose landing gear well damage looking up. Note: pressure vessel was compromised (Courtesy of FAA)