



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA21LA316



Photo 1 – View of the airplane where it came to rest. (Photo Courtesy of FAA)



Photo 2 – View of airplane from the end of the runway. (Photo Courtesy of FAA)



Photo 3 – View of the damage to the propellor and lower fuselage. (Photo Courtesy of FAA)