



Photo 1 – Digital Photograph From Pilot/Owner. Left Side View of the Helicopter Following Recovery.



Photo 2 – Digital Photograph From Airport Manager. Right Side View of a Portion of the Helicopter Following Recovery.




Photo 3 - Digital Photograph From Pilot/Owner. View Depicting Crack and Deformation To One of Four Structural 4130 Steel Tubes That Connect the Tailboom.