



Photo 1 – main wreckage



Photo 2 – skid, fuselage damaged



Photo 3 – tail rotor strike, bent blades



Photo 4 – driveshaft with burn pattern



Photo 5 – driveshaft coupling, plug