



Photo 1– front left view of main wreckage



Photo 2 – elevator bracket jammed on nylon stop.



Photo 3 – bottom view of elevator bracket jammed on nylon stop




Photo 4– nylon stop with elevator bracket impression marks



Photo 5– top view of nylon stop with elevator bracket impressions




Photo 6 – cables cutting into structure




Photo 7– elevator cable cutting into tail section



Photo 8 – tail section damage by loose cables



Photo 9 – Elevator and rudder cables loose and held with bungy cord