



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA21LA387



Photo 1 – View of Main Wreckage (Courtesy of FAA)



Photo 2 – View of Rotational Skid Marks at Point of Takeoff (Courtesy of FAA)



Photo 3 – View of Rotational Skid Marks (Courtesy of FAA)



Photo 4 – View of Separated Tailboom Section (Courtesy of FAA)