



Photo 1 – FAA Digital Photograph. Left Forward View of the Inverted Airplane at the Accident Site. Note the damage to the Left Wing, and Bottom and Side of the Fuselage near the Left Horizontal Stabilizer.



Photo 2 - FAA Digital Photograph. View of the Bottom Side of the Inboard Section of the Left Wing Noting Structural Damage.



Photo 3 – Photograph From Owner/Operator. View of the Oil Filter Element. Note the non-ferrous Particles.