



Photo 1 – view from left front



Photo 2 – view of left wing leading edge damage.