



Photo 1 – View of left side of tail boom showing buckling (Airbus Photo)



Photo 2 – View of bottom of tail boom showing buckling and cracked paint (Airbus Photo)




Photo 3 – View of right side showing buckling and cracked paint. (Airbus Photo)