



Photo 1 – canopy structure damaged



Photo 2 – propeller damaged




Photo 3 – Landing gear and firewall damage