



Photo 1 – NTSB Digital Photograph. View Looking from Main Wreckage Location to Impacted Tree (CrossHairs Depict the Impacted Tree).



Photo 2 - NTSB Digital Photograph. Left Side View of the Inverted Airplane at the Accident Site.



Photo 3 - NTSB Digital Photograph. View of the Separated Right Wing.



Photo 4 - NTSB Digital Photograph. View of the Firewall and Remains of the Engine Assembly. Note the Extensive Fire Damage.



Photo 5 - NTSB Digital Photograph. View of the Extensively Heat Damage Crankcase Halves. Note the visible Crankshaft, camshaft, and Valve Train Components.



Photo 6 - NTSB Digital Photograph. View of the No. 3 Top Spark Plug. Note the Ground Electrode Touching the Center Electrode.



Photo 7 - NTSB Digital Photograph. View Depicting the Pushrods and Pushrod Housings from the Nos. 1 and 2 Cylinders. Note the Near 90 degree Bending of Two of them.