



Photo 1 – View of engine shortly after arrival of fire personnel. (Courtesy of Pine Township)



Photo 2 – Overall view of the wreckage location showing geographic details.



Photo 3 – View of engine and propeller the following day. Note the snow was morning after the accident. (Courtesy of Textron)



Photo 4 – View of oil dip stick as discovered.



Photo 5 – View of turbo compressor.



Photo 6 – View of turbo compressor housing. Note static impact marks.



Photo 7 – View of number 4 connecting rod discovered outside of engine. (Courtesy of Textron)



Photo 8 – View of left wingtip that separated after striking trees about 200 feet from main wreckage.



Photo 9 – View of top side of engine showing 2 holes.



Photo 10 – Entire top view of engine showing holes in case and propeller spinner.



Photo 11 – View of left wing and spar during wreckage layout.




Photo 12 – View of opened engine case half and camshaft showing bearings.



Photo 13 – Overall view of condition of crankshaft after removal.