



Photo 1 – initial impact point



Photo 2 – wreckage path with scattered parts



Photo 3 - engine



Photo 4 – tail rotor and boom