



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA22FA114



Photo 1 – View of tree damage from accident airplane



Photo 2 – View of highly fragmented wreckage



Photo 3 – View of engine separated from airplane during impact sequence



Photo 4 – View of impact fragmented fuselage and empennage



Photo 5 – View of impact fragmented fuselage and empennage from opposite direction



Photo 6 – View of impact fractured tree resting on wreckage



Photo 7 – Closer view of main wreckage



Photo 8 – View of wreckage in a tree along the debris path



Photo 9 – View of scattered wreckage around and under fractured tree trunk



Photo 10 – Wreckage debris in wooded area



Photo 11 – View of fractured magneto and wreckage



Photo 12 – View of debris and fractured landing gear



Photo 13 – Close-up view of main wreckage



Photo 14 – View of highly fragmented cockpit area



Photo 15 – View of nose landing gear near remnants of cockpit



Photo 16 – Housing of gyroscopic instrument separated from cockpit control panel



Photo 17 – View of propeller blade separated from hub with chordwise abrasion on face



Photo 18 – View of engine #2 near main wreckage