

ERA22FA199

INVESTIGATION PHOTOGRAPHS



Photograph 1- Fire damaged airplane hull.



Photograph 2 - Fire damage cockpit and instrument panel



Photograph 3 - Right engine showing fire damage



Photograph 4 - Left engine showing fire damage



Photograph 5 - Fire damaged vertical and horizontal stabilizer