

ERA22FA223

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of propeller and engine where it came to rest.



Photograph 2 - View of the instrument panel.



Photograph 3 - View of the main wreckage.



Photograph 4 - View of empennage and main wreckage.