



Photo 1 – Tree Impact Damage (NTSB Photo)



Photo 2 – Main Wreckage (NTSB Photo)



Photo 3 – Right Wing (NTSB Photo)



Photo 4 – Left Wing Fragments (NTSB Photo)



Photo 5 – Angular-cut Tree Limb (NTSB Photo)



Photo 6 – Engine (NTSB Photo)



Photo 7 – Propeller Blade (NTSB Photo)



Photo 8 – Propeller Blade (NTSB Photo)



Photo 9 – Top Spark Plugs (NTSB Photo)



Photo 10 – Airspeed Indicator Face (Textron Aviation Photo)