



Photo 1 – View of left side of airplane wreckage at site



Photo 2 -View of instrument panel



Photo 3 – View of cabin section of airplane



Photo 4 – View of empennage section in foliage with browning leaves.



Photo 5 – View of recovered airplane.



Photo 6 – View of vertical and horizontal stabilizer




Photo 7 – View of the inlet side of the left fuel servo.



Photo 8 – Opposite end of left fuel servo screen passageway.



Photo 9 – View of the fuel servo screen showing contamination.