




Photo 1 – Accident site overview. Orange cones mark location of propellor wood



Photo 2 – Front view of aircraft. Note ground scarring



Photo 3 – Closeup of ground scarring



Photo 4 – Front left side of aircraft



Photo 5 – Closeup of engine. Note shattered propellor and dirt on engine



Photo 6 – Closeup of aircraft cockpit from right side



Photo 7 – Rear view of aircraft. Note damage to left wing