



Photo 1 – Fractured Powerline



Photo 2 – Top of Helicopter at Accident Site Looking Down Hill



Photo 3 – Bottom Side of Helicopter Looking Up Hill



Photo 4 – Fractured Section of Tail Boom



Photo 5 – Impact Striation Marks on White Main Rotor Blade



Photo 6 – Left Side View of Helicopter at Salvage Yard



Photo 7 – Left Side View of Helicopter at Salvage Yard



Photo 8 – Right Side View of Helicopter at Salvage Yard



Photo 9 – Exemplar Section of Powerline Cable



Photo 10 – Impact Marks/Striations to Bottom of White Main Rotor Blade




Photo 11 – Impact Marks/Striations/Arcing to Top of White Main Rotor Blade




Photo 12 – Arcing to the Trailing Edge Tip of the Red Main Rotor Blade