

ERA22FA418

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage



Photograph 2 - Engine And Propeller



Photograph 3 - Metal Fragments in Oil Sump



Photograph 5 - View of Crankshaft Through Oil Sump



Photograph 5 - Engine Teardown Examination



Photograph 6 - Fractured Connecting Rods