

N525AT

Aircraft- Vans Aircraft Inc.

Model- RV-12

S/N 12065

Engine- Rotax Model 912ULS Series

I arrived at the accident location Wednesday 10/27/2021 @ 0930. Charlton County Sheriff's Office had secured the accident site throughout the night. The aircraft came to rest directly next to roadway. The cockpit/cabin of the aircraft was destroyed by post impact fire. The R/H Wing was folded back and detached from wing fitting, the L/H Wing was attached to the fuselage and received outboard wing damage due to impacting a utility pole. The aft fuselage and tail section appeared to only have minor damage and were intact. The power plant appeared to be intact and still attached to the mounts. One composite propeller blade was located lying at the right hand side of the engine. The other two blades were not located. Due to the location of where the aircraft came to rest the on-site investigation was limited for safety reasons. The recovery team arrived @1300 and prepped the aircraft for transport.

JEFFREY
M DAVIS

Digitally signed
by JEFFREY M
DAVIS
Date: 2021.10.28
10:33:12 -04'00'