



Photo 1 – FAA Digital Photograph. View of the Airplane at the Accident Site. Note the oil Covering the Entire Length of the Exterior of the Bottom Fuselage Skin, and the Damaged Left Horizontal Stabilizer and Elevator.



Photo 2 - FAA Digital Photograph. View of the Hole in the Engine Crankcase Above the No. 6 Cylinder.



Photo 3 – Annotated FAA Digital Photograph. White Arrow Depicts upper Portion of the Separated Oil Filter and Red Arrow Points to Base of the Oil Filter Attached to the Oil Filter Adapter. Note the Impact Damaged Oil Filter.



Photo 4 - FAA Digital Photograph. View of the Oil Filter Adapter and Installed Base of Oil filter, and also Oil Filter Element Separated For the Investigation.



Photo 5 - FAA Digital Photograph. View of the Fractured Lower Portion of the Accessory Case that Accepted the Threaded Portion of the Oil Filter Adapter.