

NTSB ERA22LA048

N3VM, PA31-350

Photo Array



Photo 1 – View of the accident airplane at the accident site (Photo Courtesy of FAA)



Photo 2 – View of the left-wing damage (Photo Courtesy of FAA)



Photo 3 – View of the airplane postaccident with the landing gear retracted during functional testing (Photo Courtesy of FAA)