



## **NATIONAL TRANSPORTATION SAFETY BOARD**

Office of Aviation Safety  
Eastern Region

**Photo Array**

**ERA22LA061**



**Photo 1 – View of airplane from the right wing. (Photo Courtesy of FAA)**



**Photo 2 – View of airplane from front. (Photo Courtesy of FAA)**



**Photo 3 – View of runway scars. (Photo Courtesy of FAA)**



**Photo 4 – View of tall grass and ground scars near embankment. (Photo Courtesy of FAA)**



**Photo 5 – View of substantial damage at landing gear attachment area. (Photo Courtesy of FAA)**