

NTSB ERA22LA097

N1596U, Cessna 207

Photo Array



Photo 1: Overview of the airplane partially submerged in water as viewed during the recovery operations
(Photo Courtesy of Florida Air Recovery)



Photo 2: Overview of the airplane mostly submerged underwater at the accident site (Photo Courtesy of Florida Air Recovery)



Photo 3: Overview of the cowling and engine area after the airplane had been recovered to shore (Photo Courtesy of FAA)





Photo 4: Overview of the right wing (Photo Courtesy of FAA)



Photo 5: Overview of the engine damage near the No. 2 Cylinder (Photo Courtesy of FAA)



Photo 6: Overview of engine and damage near its aft end, concentrated near the No. 2 Cylinder (NTSB Photos)



Photos 7, 8, 9: Overview of each cylinder (NTSB Photo)



Photos 10, 11: Overview of the oil filter and the camshaft disassembled (NTSB Photo)



Photo 12: Overview of the crankshaft post disassembly (NTSB Photo)