

[ERA22LA104]


INVESTIGATION EXAM PHOTOGRAPHS



Photograph 1 - View of engine compartment prior to disassembly. (Courtesy of Lycoming)



Photograph 2 - Closeup view of hole in engine case. (Courtesy of Lycoming)



Photograph 3 - Engine crankcase halves separated. (Courtesy of Lycoming)



Photograph 4 - Counterweight roller and washer ejected. (Courtesy of Lycoming)



Photograph 5 - Counterweight, washer, and circlip. Note circlip with broken eyelets. (Courtesy of NTSB)



Photograph 6 - Fractured bearings, rods and rod bolts. (Courtesy of Lycoming)