



Office of Aviation Safety
Eastern Region

Photo Array

ERA22LA109



Photo 1 – View of airplane from left wing after recovery (Photo Courtesy of FAA)



Photo 2 – View of damage to crankcase at cylinder No. 6 (Photo Courtesy of FAA)



Photo 3 – View of engine from above before initial examination.



Photo 4 - View of the No. 6 connecting rod bearing fused to the crankshaft journal.




Photo 5 – View of No. 3 main journal bearing as seated in right side of crankcase, blocking the oil port.