

ERA22LA121

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of Airplane from Right Side (Courtesy FAA)




Photograph 2 - View of Nose Landing Gear Wheel (Right Side Facing UP, Courtesy FAA)



Photograph 3 - Tire Marks Near End of Rollout - Direction of Travel- Toward Camera (Courtesy FAA)



Photograph 4 - Damage to Engine Mount Structure (Courtesy FAA)



Photograph 5 - Fractured Landing Gear Trunnion (Courtesy FAA)



Photograph 6 - Fractured Trunnion Bolt (left) and Fitting (Right)