



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Alaska Region

Photo Array

ERA22LA139



Photo 1 – View of left wing (Photo Courtesy of FAA)



Photo 2 – View of airplane from the front looking aft (Photo Courtesy of FAA)



Photo 3 – View of engine with the cowling removed in the field where it came to rest. (Photo Courtesy of FAA)