

ERA22LA148

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Tire grooves in ground leading up to wreckage. (Courtesy of MTN Airport)



Photograph 2 - View of right side of airplane. (Courtesy of MTN Airport)



Photograph 3 - Aft view of airplane looking forward. (Courtesy of MTN Airport)



Photograph 4 - View of left wing flap damage. (Courtesy of MTN Airport)



Photograph 5 - Closeup view of left flap damage. (Courtesy of MTN Airport)



Photograph 6 - View of airplane through security fence. (Courtesy of MTN Airport)



Photograph 7 - View of landing gear in mud. (Courtesy of MTN Airport)