

ERA22LA150

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of airplane from right wing before recovery. (Courtesy of FAA)



Photograph 2 - View of airplane nose and snow-covered runway before recovery. (Courtesy of FAA)



Photograph 3 - View of airplane from right before recovery. (Courtesy of Honda Jet)




Photograph 4 - View of lower fuselage and wing damage. (Courtesy of FAA)



Photograph 5 - View of right main landing gear tire. (Courtesy of HondaJet)



Photograph 6 - View of impact damage as viewed at recovery. (Courtesy of FAA)



Photograph 7 - View of right aileron damage. (Courtesy of Airport Manager)



Photograph 8 - View of damage above left main landing gear. (Courtesy of HondaJet)