



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA22LA171




Photo 1 – View of the fracture surface on the step (Photo courtesy of FAA)




Photo 2 – View of the separated left main landing gear (Photo courtesy of FAA)