



Photo 1 – main wreckage, inverted (FAA)



Photo 2 – case fractured



Photo 3 – case fractured from inside



Photo 4 – metal parts at bottom of case half



Photo 5 – piston rod, fractured with bearing destroyed



Photo 6 – crankshaft, pitted



04/07/2022 14:31

Photo 7 – vacuum pump, coupling destroyed