



Millicent Hill
Aviation Accident Investigator
Office of Aviation Safety

Date: April 13, 2022

Subject: ERA22LA187

Contact: Ken Wolf, pilot

Mr. Wolf stated he had his Lancair converted into the LX7. He said according to guidance if stored outside the windows should be replaced every 15 years, if stored inside they should be replaced every 30 years. He had ordered the replacement windows, which would have been installed, but the accident occurred before they could be replaced.