



NTSB ERA22LA215

N46TA, Cessna 414

Investigative Photographs



Photo 1: Overview of the substantial damage sustained to the airplane (Photo Courtesy of FAA)



Photo 2: Overview of the ravine the airplane traveled down after departing the runway surface (Photo Courtesy of FAA)



Photo 3: Overview of the substantial damage sustained to the airplane (Photo Courtesy of FAA)



Photo 4: Overview of the substantial damage sustained to the airplane (Photo Courtesy of FAA)



Photo 5: Overview of the cockpit panel (Photo Courtesy of FAA)



Photo 6: View of the elevator bellcrank and the avionics tray (Photo Courtesy of FAA)




Photo 7: View of the KX-155 avionics tray (Photo Courtesy of FAA)