



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA22LA245



Photo 1 – View of Inverted Airplane from Left Side (Courtesy of FDK Airport Manager)



Photo 2 – View of Inverted Airplane from Right Side – Note Damage to Upper Wing (Courtesy of FDK Airport Manager)



Photo 3 – View of Inverted Airplane from Front (Courtesy of FDK Airport Manager)