



NTSB ERA22LA247

C150F, N8919S

Investigative Photographs



Photo 1: Overview of the substantial damage sustained to the airplane's right wing (Photo Courtesy of FAA)



Photo 2: Overview of the nose gear postaccident (Photo Courtesy of FAA)



Photo 3: Forward view of the nose landing gear (Photo Courtesy of FAA)




Photo 4: Overview of the left steering connecting rod (Photo Courtesy of FAA)



Photo 5: Overview of the right steering connecting rod remaining connected (Photo Courtesy of FAA)




Photo 6: Overview of the left steering connecting rod (Figure from report)