

ERA22LA249

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Firewall damage (Courtesy of FAA)



Photograph 2 - Rudder damage (Courtesy of FAA)



Photograph 3 - Rudder damage (Courtesy of FAA)



Photograph 4 - Right wing damage (Courtesy of FAA)



Photograph 5 - Right wing damage (Courtesy of FAA)



Photograph 6 - Header tank fuel shutoff valve (Courtesy of FAA)