



Photo 1 – Front View of Airplane on Trailer (credit FAA).



Photo 2 – Damage to the Leading Edge of the Left Wing (credit FAA)