

ERA22LA258

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the airplane inverted where it came to rest. (Courtesy of FAA)



Photograph 2 - View of the gascolator. (Courtesy of FAA)



Photograph 3 - View of staining aft of right wing fuel sump. (Courtesy of FAA)