



Photo 1 – View of right horizontal stabilizer damaged



Photo 2 – View of the damaged left main landing gear.