



Photo 1 – Front View of Airplane on Runway at HEF (FAA)



Photo 2 – External Damage to the Forward Engine Area on Right Side (FAA)



Photo 3 – Damage Aft of the Firewall (FAA)