

NTSB ERA22LA296

N7215D, American Champion 8KCAB

Photo Array



Photo 1: Accident airplane, forward view of airplane in hangar. (Photo Courtesy of FAA)



Photo 2: Accident airplane, left wheel strut damage, forward view. (Photo Courtesy of FAA)



Photo 3: Accident airplane, left wheel strut damage, aft view. (Photo Courtesy of FAA)



Photo 4: Accident airplane, sheared left main landing gear through bolt. (Photo Courtesy of FAA)



Photo 5: Accident airplane, rudder damage. (Photo Courtesy of FAA)



Photo 6: Accident airplane, rudder damage. (Photo Courtesy of FAA)