



**Photo 1 – Digital Photograph From Lockwood Aviation. Left Forward Quartering View of the Wreckage Following Recovery.**



**Photo 2 - Digital Photograph From Lockwood Aviation. Right Forward Quartering View of the Wreckage Following Recovery. Note the Structural Damage to the Right Wing.**



**Photo 3 - Digital Photograph From Lockwood Aviation. View Showing the Impact Damaged Right Aileron Rod End.**