

NTSB ERA22LA306

N7883P, Piper PA-24

Photo Array



Photo 1: Damage to the airplane's fuselage (Photo Courtesy of FAA)



Photo 2: Damage to the airplane's fuselage (Photo Courtesy of FAA)



Photo 3: Hole in the airplane fuselage abeam the nose landing gear tunnel wall (Photo Courtesy of FAA)



Photo 4: Damage to the airplane's fuselage (Photo Courtesy of FAA)