

ERA22LA307

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Postaccident view of wreckage (Courtesy of FAA)




Photograph 2 - Postaccident view of wreckage (Courtesy of Anglin's Aircraft Recovery)



Photograph 3 - Impact damage to left wing (Courtesy of FAA)



Photograph 4 - Deteriorated fuel injector airbox boot (Courtesy of Lycoming)



Photograph 5 - Deteriorated fuel injector airbox boot



Photograph 6 - Deteriorated fuel injector airbox boot