



Photo 1 – Front View of Left Propeller



Photo 2 – Wrinkling of Lower LH Wing Structure