

ERA22LA312

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left side profile view of damaged airplane. (Courtesy of FAA)



Photograph 2 - Front view of airplane damage and fractured left wing. (Courtesy of FAA)



Photograph 3 - View of damaged and shattered propeller blades. (Courtesy of FAA)