



Photo 1 – Right Side View of Damage to Tail Boom (FAA)



Photo 2 – Bent Tail Rotor Drive Shaft (FAA)